


60.130-1291
00MRA0622

AMENDMENTS TO THE SPECIFICATION:

Please amend the specification as follows:

-  [27] Motor assembly 14 sits in motor recess 26 with shaft ~~21~~31 engaging and being supported by the hole within boss 42.